

Axis	Type	Features/Envelope
5	HORIZONTAL MILLING CENTER	<ul style="list-style-type: none"> • Simultaneous control • Taper 50-4,000 rpm • Travel X,Y,Z > 59"x49"x39" • A,B > 95°, 360 °
5	HORIZONTAL MILLING CENTER	<ul style="list-style-type: none"> • 15,000-rpm Spindle, 40 taper • Travel X,Y,Z > 30"x20"x20" • B > +110°, -35° • C > 360°
4	HORIZONTAL MILLING CENTER	<ul style="list-style-type: none"> • 11 Pallet - Vertical • Taper 40-12,000 rpm • Travel X,Y,Z > 20"x23"x20"
4	HORIZONTAL MILLING CENTER	<ul style="list-style-type: none"> • Taper 50-12,000 rpm • Travel: X,Y,Z > 39"x32"x30"
4	HORIZONTAL MILLING CENTER	<ul style="list-style-type: none"> • Taper 40-12,000 rpm • Travel X,Y,Z > 27"x27"x27"
4	VERTICAL MACHINING CENTER	<ul style="list-style-type: none"> • Taper 40-7,500 rpm • Travel X,Y,Z > 64"x40"x30"

Axis	Type	Features/Envelope
3	HORIZONTAL MILLING CENTER	<ul style="list-style-type: none"> • Taper 50-4,500 rpm • Travel X,Y,Z > 30"x20"x20"
2	VERTICAL TURN CENTER	<ul style="list-style-type: none"> • Table Diameter in(mm) 57.08(1450) • Max Swing in(mm) 78.74(2000) • Max cutting height in(mm) 61.02(1550) • Max cutting diameter in(mm) 78.74(2000) • Max Table Load lb(kg) 17600(8000) • Taper 50 rpm
4	HORIZONTAL MILL / TURN CENTER	<ul style="list-style-type: none"> • Swing: 28 " dia • Centers: 39 " • Taper 45-3,000 rpm • Travel: X,Y,Z > 19"x9"x41"
4	HORIZONTAL MILL / TURN CENTER	<ul style="list-style-type: none"> • Swing: 20 " dia • Centers: 28 " • Taper 45-4,000 rpm • Travel X,Y,Z > 24"x6"x40"
2	HORIZONTAL TURN CENTER	<ul style="list-style-type: none"> • Swing: 17 " dia • Centers: 20 " • Auto-Bar Feeder
2	HORIZONTAL TURN CENTER	<ul style="list-style-type: none"> • Swing: 20 " dia • Centers: 24 " Auto-Bar Feeder

4	VERTICAL MACHINING CENTER	<ul style="list-style-type: none"> • Taper 40-7,500 rpm • Travel X,Y,Z > 64"x32"x30"
4	HORIZONTAL MACHINING CENTER	<ul style="list-style-type: none"> • Taper 40-7,500 rpm • Travel X,Y,Z > 50"x20"x25"
